

PCB MOUNTABLE TOROIDAL TRANSFORMERS

PRINTBARE RINGKERNTRANSFORMATOREN



Alttec GmbH
Sauerzapfstraße 14
92507 Nabburg

TEL +49 / (0) 9433 / 205 760 - 0
FAX +49 / (0) 9433 / 205 760 - 29
MAIL info@alttec.de

WEB www.alttec.de




PCB MOUNTABLE TOROIDAL TRANSFORMERS

SERIES 60XX






Für alle Typen gelten folgende Werte:
Specifications valid for all types:
Input voltage 2 x 115 V, 50/60 Hz
HV Test voltage 4.0 kV (prim - sec)
Ambient temperature T 70/F
Isolation class VDE F 155° C
Approbation VDE, UL, CE

CIRCUIT DIAGRAM

CASE FOR 1.6 - 25 VA



CASE FOR 35 & 50 VA



1.6 VA	Part Number	Secondary		No load voltage		Resistance 20 °C	L x W x H = 39.6 x 39.6 x 18.5 mm X x Y = 35.56 x 35.56 mm Weight total = 80 g Weight Cu = 20 g Efficiency = 77 % External Fuse 32 mA (stb) at 230 V Fixing = M4 or self tapping screw
	L01-6000	2 x 7 V	114 mA	2 x 9 V	2 x 8.8 Ω		
	L01-6001	2 x 9 V	89 mA	2 x 11.6 V	2 x 15.8 Ω		
	L01-6002	2 x 12 V	67 mA	2 x 15.4 V	2 x 26.9 Ω		
	L01-6003	2 x 15 V	53 mA	2 x 19.3 V	2 x 43.4 Ω		
	L01-6004	2 x 18 V	44 mA	2 x 23.4 V	2 x 65.9 Ω		
3.2 VA	* L01-6005	2 x 22 V	36 mA	2 x 28.2 V	2 x 88.1 Ω		
	Part Number	Secondary		No load voltage		Resistance 20 °C	L x W x H = 44.7 x 44.7 x 19.5 mm X x Y = 40.64 x 40.64 mm Weight total = 110 g Weight Cu = 26 g Efficiency = 70 % External Fuse 32 mA (stb) at 230 V Fixing = M4 or self tapping screw
	L01-6010	2 x 7 V	229 mA	2 x 10.2 V	2 x 7.0 Ω		
	L01-6011	2 x 9 V	178 mA	2 x 13.0 V	2 x 11.3 Ω		
	L01-6012	2 x 12 V	133 mA	2 x 17.3 V	2 x 20.7 Ω		
	L01-6013	2 x 15 V	107 mA	2 x 21.4 V	2 x 28.9 Ω		
	L01-6014	2 x 18 V	89 mA	2 x 24.9 V	2 x 45.4 Ω		
5 VA	* L01-6015	2 x 22 V	73 mA	2 x 31.3 V	2 x 62.2 Ω		
	Part Number	Secondary		No load voltage		Resistance 20 °C	L x W x H = 49.7 x 49.7 x 19.5 mm X x Y = 45.72 x 45.72 mm Weight total = 144 g Weight Cu = 33 g Efficiency = 68 % External Fuse 50 mA (stb) at 230 V Fixing = M4 or self tapping screw
	L01-6020	2 x 7 V	357 mA	2 x 9.7 V	2 x 4.0 Ω		
	L01-6021	2 x 9 V	278 mA	2 x 12.4 V	2 x 6.5 Ω		
	L01-6022	2 x 12 V	208 mA	2 x 17.0 V	2 x 12.3 Ω		
	L01-6023	2 x 15 V	167 mA	2 x 21.3 V	2 x 19.0 Ω		
	L01-6024	2 x 18 V	139 mA	2 x 24.8 V	2 x 28.8 Ω		
7 VA	* L01-6025	2 x 22 V	114 mA	2 x 30.5 V	2 x 39.1 Ω		
	Part Number	Secondary		No load voltage		Resistance 20 °C	L x W x H = 49.7 x 49.7 x 23.1 mm X x Y = 45.72 x 45.72 mm Weight total = 174 g Weight Cu = 36 g Efficiency = 74 % External Fuse 63 mA (stb) at 230 V Fixing = M4 or self tapping screw
	L01-6030	2 x 7 V	500 mA	2 x 9.5 V	2 x 2.5 Ω		
	L01-6031	2 x 9 V	389 mA	2 x 12.2 V	2 x 4.1 Ω		
	L01-6032	2 x 12 V	292 mA	2 x 16.2 V	2 x 7.7 Ω		
	L01-6033	2 x 15 V	233 mA	2 x 20.3 V	2 x 12.0 Ω		
	L01-6034	2 x 18 V	194 mA	2 x 24.3 V	2 x 17.9 Ω		
10 VA	* L01-6035	2 x 22 V	159 mA	2 x 29.7 V	2 x 24.4 Ω		
	Part Number	Secondary		No load voltage		Resistance 20 °C	L x W x H = 55.0 x 55.0 x 26.0 mm X x Y = 50.80 x 50.80 mm Weight total = 252 g Weight Cu = 45 g Efficiency = 82 % External Fuse 80 mA (stb) at 230 V Fixing = M4 or self tapping screw
	L01-6040	2 x 7 V	714 mA	2 x 8.3 V	2 x 1.0 Ω		
	L01-6041	2 x 9 V	556 mA	2 x 10.8 V	2 x 1.7 Ω		
	L01-6042	2 x 12 V	417 mA	2 x 14.4 V	2 x 3.2 Ω		
	L01-6043	2 x 15 V	333 mA	2 x 18.0 V	2 x 5.0 Ω		
	L01-6044	2 x 18 V	278 mA	2 x 21.7 V	2 x 7.5 Ω		
15 VA	* L01-6045	2 x 22 V	227 mA	2 x 26.3 V	2 x 10.3 Ω		
	Part Number	Secondary		No load voltage		Resistance 20 °C	L x W x H = 60.0 x 60.0 x 26.3 mm X x Y = 55.88 x 55.88 mm Weight total = 304 g Weight Cu = 57 g Efficiency = 80 % External Fuse 100 mA (stb) at 230 V Fixing = M4 or self tapping screw
	L01-6050	2 x 7 V	1071 mA	2 x 8.9 V	2 x 0.85 Ω		
	L01-6051	2 x 9 V	833 mA	2 x 11.1 V	2 x 1.3 Ω		
	L01-6052	2 x 12 V	625 mA	2 x 14.8 V	2 x 2.3 Ω		
	L01-6053	2 x 15 V	500 mA	2 x 18.5 V	2 x 3.1 Ω		
	L01-6054	2 x 18 V	417 mA	2 x 22.2 V	2 x 5.3 Ω		
25 VA	* L01-6055	2 x 22 V	341 mA	2 x 27.2 V	2 x 7.4 Ω		
	Part Number	Secondary		No load voltage		Resistance 20 °C	L x W x H = 60.0 x 60.0 x 37.5 mm X x Y = 55.88 x 55.88 mm Weight total = 435 g Weight Cu = 85 g Efficiency = 83 % External Fuse 100 mA (stb) at 230 V Fixation = M4 or self tapping screw
	L01-6060	2 x 7 V	1785 mA	2 x 8.3 V	2 x 0.4 Ω		
	L01-6061	2 x 9 V	1377 mA	2 x 10.7 V	2 x 0.7 Ω		
	L01-6062	2 x 12 V	1041 mA	2 x 14.3 V	2 x 1.3 Ω		
	L01-6063	2 x 15 V	832 mA	2 x 17.8 V	2 x 2.0 Ω		
	L01-6064	2 x 18 V	694 mA	2 x 21.4 V	2 x 2.7 Ω		
35 VA	* L01-6065	2 x 22 V	568 mA	2 x 26.2 V	2 x 4.1 Ω		
	Part Number	Secondary		No load voltage		Resistance 20 °C	L x W x H = 72.0 x 72.0 x 37.5 mm X x Y = 66.04 x 66.04 mm Weight total = 525 g Weight Cu = 187 g Efficiency = 82 % External Fuse 200 mA (stb) at 230 V Fixing = M5 or self tapping screw
	L01-6070	2 x 7 V	2500 mA	2 x 8.2 V	2 x 0.19 Ω		
	L01-6071	2 x 9 V	1944 mA	2 x 10.6 V	2 x 0.32 Ω		
	L01-6072	2 x 12 V	1458 mA	2 x 14.0 V	2 x 0.53 Ω		
	L01-6073	2 x 15 V	1167 mA	2 x 17.6 V	2 x 0.84 Ω		
	L01-6074	2 x 18 V	972 mA	2 x 20.9 V	2 x 1.10 Ω		
50 VA	* L01-6075	2 x 22 V	795 mA	2 x 25.7 V	2 x 1.34 Ω		
	Part Number	Secondary		No load voltage		Resistance 20 °C	L x W x H = 82.4 x 82.4 x 37.5 mm X x Y = 76.2 x 76.2 mm Weight total = 685 g Weight Cu = 209 g Efficiency = 85 % External Fuse 315 mA (stb) at 230 V Fixing = M5 or self tapping screw
	L01-6080	2 x 7 V	3571 mA	2 x 8.1 V	2 x 0.13 Ω		
	L01-6081	2 x 9 V	2777 mA	2 x 10.4 V	2 x 0.20 Ω		
	L01-6082	2 x 12 V	2083 mA	2 x 13.9 V	2 x 0.34 Ω		
	L01-6083	2 x 15 V	1666 mA	2 x 17.3 V	2 x 0.54 Ω		
	L01-6084	2 x 18 V	1389 mA	2 x 20.8 V	2 x 0.82 Ω		
50 VA	* L01-6085	2 x 22 V	1136 mA	2 x 25.4 V	2 x 1.25 Ω		

* keine VDE Zulassung without VDE approval

